

July 2018

FIRMWARE UPDATE FILE FOR OPTILINK ECU

This document is providing access to a file to update OptiLink ECU with advanced functional safety features.

The update file is available under below link:


<http://wabco.info/i/769>

Once you finish downloading the file, extract the file and save the file "OptiLink_AP_DPL2_OL010204.hex" at your computer.

Choose "System" → "ECU update" → "OptiLink..." in the menu of TEBS E PC Diagnostic Software




Click "Read from file"




July 2018

Choose "*OptiLink_AP_DPL2_OL010204.hex*" and click "*Open*"




Click "*Write to ECU*"



July 2018

Upgrading process will start



After the "Download status" reaches 100%, updating process is finished.