


Repair for the new generation of coupling heads with filter for trailers only with repair kit 952 201 920 2

The new generation of coupling heads with filter for trailers introduced in [Market Information 7016](#) (15 June 2007) must only be repaired using repair kit 952 201 920 2.

The repair kit is currently in preparation.

Until this repair kit is made available, the entire coupling head needs to be replaced if a problem occurs.



The following coupling heads are affected:

Description	Coupling heads New generation
Yellow, integrated filter	952 201 011 0
Red, integrated filter	952 201 012 0
Yellow, integrated filter, pressure test connection	952 201 013 0
Yellow, integrated filter, pressure test connection, connector	952 201 014 0
Red, integrated filter, pressure test connection, connector	952 201 015 0
Yellow, integrated filter, without hexagon nut	952 201 016 0
Red, integrated filter, without hexagon nut	952 201 017 0

The repair kit will include 2 sealing rings with different contours.

For repair it is essential that you note the contour of the installed sealing ring and replace it with the identical spare part from the repair kit.

Installing an incorrect sealing ring will cause a malfunction of the braking system.

We will inform you as soon as the repair kit is available.