

Market Information



1st June 2004

Changement to Fixation of Air Spring 951 812 721 0 Replacement Air Spring 951 811 712 0

To avoid improper mounting of air spring 951 812 721 0, we changed the fixation threads at the bottom of the piston. Previously, additional to the central female thread, 4 further threads were foreseen for optional usage. Since no vehicle manufacturer used them they have now been taken away.

The right of amendment is reserved © copyright: WABCO' 2003
No part of this publication may be reproduced without our prior permission.

Änderungen bleiben vorbehalten © Copyright: WABCO' 2003
Nachdruck - auch auszugsweise - nur mit unserer Genehmigung.

WABCO	Scheme	OE
<p>Air spring complete 951 812 721 0</p> <p>Bellow 896 130 103 4</p>	<p style="text-align: center;">previous fixation</p>  <p style="text-align: center;">new fixation</p> 	<p>Fruehauf UJB 02358 UJY 0099 Trailor M001774 Samro 25324 Trouillet HT 18002</p>

Replacement of Air Spring 951 811 712 0 with 951 811 763 0

The difference between the two air springs is given with to deviating fixation threads only. The replacement will suit in most cases.

Previous solution

WABCO	Scheme	OE
<p>Air spring complete 951 811 712 0 (no longer available)</p> <p>Bellow 896 130 107 4</p>		<p>BPW 30K</p> <p>05.429.41.14.1 05.429.41.23.1 05.429.41.53.1 05.429.42.19.1 05.429.41.27.1 05.429.42.17.1 05.429.42.08.1</p>

Replacement 951 811 763 0

WABCO	Scheme	OE
<p>Air spring complete 951 811 763 0</p> <p>Bellow 896 130 107 4</p>		<p>BPW</p> <p>05.429.41.14.1 05.429.41.23.1 05.429.41.27.1 05.429.41.53.1 05.429.42.19.1 05.429.43.21.0</p>