


Corrective actions details – Update R/R Software to RR000112

Update of Router/Repeater Software necessary by using PC diagnostic CAN Router / Repeater diagnostic SW V1.01. Please download via this link:

http://inform.wabco-auto.com/intl/pdf/zip/2461220512_a_rr000112_dpl2.zip

1) Go to the Menu *System* => *ECU Update*



2) Select *Read from file*.

3) Select the ECU Update .hex file.

4) Select *Write to ECU*.

5) Follow the instructions of the PC diagnostic.

→ After successful finalizing the update reset the R/R ECU