

472 125 707 0 replaced by 472 173 701 0

With old 472 125 7070 the solenoid could be turned to adapt to the plug position.
This is not possible with replacement 472 173 701 0.
If adaptation is needed, use equal valve 472 173 703 0 having solenoid in 180° position.

