

### Trailer Emergency Valve 971 002 802 0 Alternative 971 002 805 0



**971 002 805 0  
with repair unit 971 002 921 2  
with software status C1, C2**



**971 002 805 0  
with repair unit 971 002 922 2  
with software status C3, D**

For the spare parts market, the trailer emergency valve 971 002 802 0 will be in case of pneumatic failure replaced by 971 002 805 0.

Pneumatic failures can be caused from:

- Leakage in driving position at the exhaust ⇒ Contamination at the / or defective supply valve
- Leakage in hand brake position ⇒ Contamination at the supply valve
- Leakage over yellow coupling head ⇒ Mechanical defect inside the Trailer emergency valve

The 971 002 805 0 do not has electrical components.  
Mounting dimensions and pneumatical ports are equal.

For the 971 002 805 0, depending on the software status of the TEBS a wiring harness with sensor and/or pressure switch is required. (see also market info from 01.03.2004)

**All trailer emergency valves are shipped with a information sheet showing wiring diagrams of both types of repair units.**

**The repair units are as follows:**

**971 002 921 2 with software status C1, C2  
971 002 922 2 with software status C3, D**

The 971 002 805 0 is for the Aftermarket only.

In case of pneumatical failures at the 971 002 802 0, the time of warranty starts with the production date.