

New update for Trailer EBS E Diagnostic Software

After week 50/2009 Trailer EBS E modulators are produced as a new version, E 1.5.

Affected part numbers will include 480 102 06x 0 (Trailer EBS E Premium) and 480 102 03x 0 (Trailer EBS E Standard).

The E 1.5 version enables new functionality within the modulator (Further information on this will be released in the near future).

Version E 1.5 modulators requires the new **Trailer EBS E diagnostic software version 1.11**. Since version E 1.5 modulators will be delivered into vehicle manufacturers and the aftermarket from week 50/2009 onwards, it will be required that you download and install the new diagnostic program as soon as possible to avoid problems with future diagnosis and programming. You can access the download area by clicking the [link](#).



No new Activation or PIN required

The new Diagnostic Software does not require a new activation. The PIN Version 100 of the new program is also the same PIN as was used with the old version 1.03.

Users of our Diagnostic Subscription can download the actual version now in multiple languages. If your desired language is not available yet, you can install alternative versions as an interim solution.

Diagnostic Newsletter notifies you about new languages

With subscribing to our Diagnostic Newsletter you are automatically informed via mail about new or updated software and its language versions. Use this [Link](#) to order the newsletter.

Further information

Please read more by clicking the links: about [Software Subscription](#), [Activation of Diagnostic Software](#), and about [PIN assignment](#).